UNCLASSIFIED proved For Research 2003/04/29 : CIA-RD 24-069 NEW 5012-2 SECRET				
ROUTING AND RECORD SHEET				
SUBJECT: (Optional) Bldg+6r 3-1 FROM: EXTENSION NO. Cerveral)				
FROM:			EXTENSION	NO. (Ceneral)
Deputy Director (Support)				DATE 26 April 1963
TO: (Officer designation, room number, and building)	er designation, room number, and DATE		OFFICER'S	COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)
1	RECEIVED	FORWARDED		To whom: Down of this decision did decir community
Chief, Logistics Services Division 2E24 HQ				George:
2.				When I briefed the Executive
3.			-	Committee on the attached this morning, it was noted that on many occasions when elevators, and
4.				particularly the private elevator, are out of order no signs are posted to this effect.
5 .				Please ensure that this is
6.				corrected without delay.
7.				Signed
8.				LKW
9.				Att: Note dtd 18 Apr 63 to Colonel White fr Mr. Lloyd re Director private elevator (DD/S 63-1742)
10.				
10.				DD/S:LKW:sbo Distribution: 0 - Adse w/O of 63-1742 1 - DD/S subject w/T of 63-1742 1 - DD/S chrono
11.				
12.				
13.				
14.				
15.				

Approved For Release 2003/04/29 : CIA-RDP84-00780R000100170012-2

18 April 1963

MEMORANDUM FOR: Colonel White

SUMMECT

: Director's Private Elevator

1. Arrangements have been made with the Otis Elevator Company to install an override control on the private elevator on the evenings of 29 and 30 April. Work will begin each day at 1800 hours and continue will executionately 0200 hours the next morning. The elevator will be in operation as usual on the 30th until 1800 hours.

- 2. The Director will be away during this time, but you might want to alert General Carter and Kirk. We tried to postpone the start of this work until 2000 hours, but these men are really working overtime and since they have just completed a full day's work and have to go to work again on the day shift, they don't went to sit around for two hours.
- 3. Incidentally, should you be asked, the estimated cost of this work is approximately \$600, including about \$170 in evertime.

131

H.G.L.